

ENGINEERING CHANGE NOTICE
DART AEROSPACE LTD

MPF

Date: 09.09.23	Job No.: 00269	ADR Yes/No: N	ADR Date:	ECN #: 09- 677
Product No.: D130-787		Created By: KB	Approved By: <i>[initials]</i>	
Product Name: TAS Installation		Checked By: <i>[initials]</i>	General Manager Approval:	NA

Distribution	Reqd	Resp	Initial / Date
Production Manager	Y	KJ	
Production Engineering Coord	Y	EC/DD	
Production Document Control	Y	BG	
Customer Technical Support	N		

Distribution	Reqd	Resp	Initial / Date
DQA / QA Coord	N		
QC Coordinator	N		
Marketing	Y	SW	
Customer Order Processing	N		

Reason for Change: Change P/N LED-41-14-ED-E05LM to LED-42-14-ED-E05LM

Documents Affected:

DSI 9481 REV. A
MDL-D130-787 REV. D

PARTS MUST COMPLY

PREVIOUS PARTS SATISFACTORY

#	Quality Assurance Actions	Reqd	Resp	Notes	Complete
1	Notify Previous Customers	N			
2	Notify Eurocopter France	N			
3		N			

#	Engineering Actions	Reqd	Resp	Notes	Complete
4	Required Documents/Drawings Under Review	Y			
5	Update Product Compatiblity Matrix	N			
6	Create Eurocopter Form (FEE)	N			
	Notify TC / FAA of Change	N			

#	Document Control Actions	Reqd	Resp	Notes	Complete
8	Move Electronic Files	Y	KJ		09.10.05 <i>[initials]</i>
9	Update Blue/Pink/DSI Folder and Electronic Files	Y	KJ		09.10.05 <i>[initials]</i>
10	Update Controlled PDF Files	Y	KJ		09.10.05 <i>[initials]</i>
11	Update Master Document List (MDL)	Y	KB	MDL-D130-787 REV. D	09.10.05 <i>[initials]</i>
12	Update Document Record (DR)	Y	KJ	Rev. B	09.10.05 <i>[initials]</i>
13	Update Product Development Summary	N			
14	Update QSI 021 and/or STC Approval List	N			
15	Update Parts / STC Database	N			
16	Update / Verify ARC Database	N			
17	Create / Update Change Record Form	N			
18	Create / Update PPP's	N			
19	Update Document Control Database / Laminated Dwgs	N			
20	Update Grey Project Binder	Y	KJ		09.10.05 <i>[initials]</i>
21	Update D-Part/M-Drawing/DSI/DEO Master Binders	Y	KJ		09.10.05 <i>[initials]</i>
22					
23					

Description / Action:

ENSURE ALL IN STOCK LED-41-14-ED-E05LM GET-NEW SWITCH BODY LED-42-14.

UPDATE ROUTING/ESTIMATE/BOM FOR D130-787-013 TO MATCH DSI 9481.

ENSURE ALL D130-787-013 GOING INTO STOCK INCLUDE LED-42-14-ED-E05LM PER DSI 9481

TO CORRECT CURRENT PARTS IN STOCK, ORDER LED-42-14 AND REPLACE CURRENT LED-41-14-ED-B05LM SWITCH BODIES WITH LED-42-14 SWITCH TO REPLACE THE SWITCH BODIES:

- 1) REMOVE LED CAP FROM P/N LED-41-14-ED-B05LM.
- 2) INSTALL LED CAP ON P/N LED-42-14.
- 3) RELABEL PART LED-42-14-ED-B05LM.
- 4) RETURN TO STOCK.

52701

ECN Verified & Complete: _____

Date: _____